


FIG. 1



10

50

60

61

62

26

25

29

25₁

21

21₂

20

28


55

W'

Wafer guide up and down


Quick drain

FIG. 4



5/11

FIG. 5




6/11

FIG. 6

	Rinsing		Drying1	Drying2	Drying3
HF Dip					
DIW					
DIW water-saving					
Slow up Speed					
Purge N ₂					
Quick Drain					
Porous plate _{IN}					
IPA supply				N ₂ IPA	
Dry N ₂					


7/11

FIG. 7



8/11

FIG. 8



9/11

FIG. 9





FIG. 10



11/11

FIG. 11

